

**Zlin Aviation S.R.O.**

2. Kvetna 685  
763 61 Napajedla  
Czech Republic

<b>Safety Alert</b>	<b>N°03</b>	<b>06 September 2007</b>
---------------------	-------------	--------------------------

**MANDATORY**

- **Airplanes affected:**  
all Savage Aircrafts and models
- **Subject:**  
Replacement of rudder's turnbuckles.

Change 5 mm turnbuckle with 5,75 mm turnbuckles using mandatory the bolts AN3-7A of the Kit.change only the pin with the bolts in the airplanes where 5,75 mm turnbuckles are installed.

- **Reason:**  
Faulty pins have been detected.
- **Compliance:** Issue date of SA, upon reception of the replacement kit
- **Material required:** kit with all necessary material is delivered.
- **Accomplishment:**
  1. dismantle old turnbuckles
  2. change old turnbuckles using the kit material
  3. make a rudder setting and make safety wire on the turnbuckles

**For the airplanes that have new turnbuckles installed:**

Change the secure pin of the turnbuckles with the bolts that there are in the kit.